

## ECS/EMD Configuration Change Request

Page 1 of

Page(s)

1. Originator Maryellen Corbett	2. Log Date: 10/28/03	3. CCR #: 03-0725	4. Rev: —	5. Tel: 301 925-0703	6. Rm #:	7. Org. COTS
8. CCR Title: Baseline Update October 2003 (#20)						
9. Originator Signature/Date Maryellen Corbett /s/ 10/27/03			10. Class II	11. Type: CCR	12. Need Date: 10/31/2003	
13. CCR Sponsor Signature/Date Carolyn Whitaker /s/ 10/28/03			14. Category of Change: Update ECS/EMD Baseline Doc.		15. Priority: (If "Emergency" fill in Block 27). Routine	
16. Documentation/Drawings Impacted (Review and submit checklist): See attached page			17. Schedule Impact:		18. CI(s) Affected:	
19. Release Affected by this Change: EMD		20. Date due to Customer:		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other:						
23. Problem: (use additional Sheets if necessary) Some baseline inconsistencies have been identified. These may involve baseline updates and/or installation/removal of COTS products to resolve identified baseline inconsistencies.						
24. Proposed Solution: (use additional sheets if necessary) Provide baseline red-lines and/or ECOs to resolve identified discrepancies. Attached sheet provides summary of baseline and system administration changes. These changes are also included in the ECO instructions for resolution of identified baseline discrepancies.						
25. Alternate Solution: (use additional sheets if necessary) Accept an inconsistent baseline and installations						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Inconsistent baseline and installations						
27. Justification for Emergency (If Block 15 is "Emergency"):						
28. Site(s) Affected: <input type="checkbox"/> EDF <input checked="" type="checkbox"/> PVC <input type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input checked="" type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:			30. Work Assigned To:		31. CCR Closed Date:	
32. SCDV CCB Chair (Sign/Date): Byron Peters /s/ 10/30/03			Disposition: <span style="border: 1px solid red; color: red;">Approved</span> App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
33. EDF CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS			

## ADDITIONAL SHEET

**CCR #:** 03-0725    **Rev:** —    **Originator:**

**Telephone:**                      **Office:**

**Title of Change:** Baseline Update October 2003 (#20)

### CM Documents:

910-TDA-003: COTS Version Map  
910-TDA-023: Critical COTS List  
910-TDA-030: PERL 5.6.1 for PC  
910-TDA-030: Autosys Remote Agent  
920-TDP-002: PVC HW/SW Map  
920-TDV-002: VATC HW/SW Map

### Baseline Documentation updates ONLY:

1. Update IRIX OS to 6.5.20 for p0drg01. Upgrade installed for testing.
2. Update path for JNI\_FC & SCSI Drive to /opt/JNIfcaw. There are only 2 instances of this in the PVC and both are installed in the directory specified.
3. Remove iPlanet 6.0 from the baseline of p2acs06. Product is not currently installed. This product was identified for this host in the early stages of Sun Consolidation, but is no longer required for this host.
4. Add the following automounted COTS to the baseline of p2acs06, as they would be utilized by this custom code host:  
Open Client 12.0 EBF 9917  
PERL 5.6.1  
TCI/tk 83.3
5. Add the following patches to the baseline of p2ins02:  
Remedy\_arserverd\_Patch #1098  
Remedy\_aruser\_Patch #1105  
Patches are correctly installed.
6. Update the SANergy version on p0acg05 to 3.2.1.32. This is the correct baseline version and it is correctly installed.
7. Remove SANergy from the baseline of p2acs03. SANergy is not currently installed and should not be baselined for this COTS product.
8. Add WU FTP to the baseline of t1mss06. This COTS product had been inadvertently left off the baseline to reconfigure t1mss06 as a Data Pool host.
9. Remove PERL 5.6.1 from the baseline of g0dip03, n0dip04, l0dip03, p0dip04 and t1dpp02. This is a duplicate name. Active Perl 5.6.1 remains on the baseline for these machines. PERL and Active Perl are duplicate names for the same delivery.
10. Remove Autosys Remote Agent from the baseline of the following hosts as this COTS is not used at GSFC and NSIDC:
  - a. g0pls03
  - b. n0spg03
  - c. g0spg01
  - d. g0spg10

### Landover Infrastructure Administrative Updates:

1. Remove SANergy 3.2.1.6 from p0dig06. Product is not baselined or required for this host.
  2. Remove obsolete Forte 6.1 compilers from p2acs06.
- 9